

KENTUCKY HISTORIC RESOURCES
INDIVIDUAL SURVEY FORM
(KHC 2002-1)

COUNTY Lewis _____
RESOURCE # Lw-57
RELATED GROUP # _____
EVALUATION I _____
SHPO EVALUATION U
DESTROYED _____

For instruction, see the Kentucky Historic Resources Survey Manual.

1. NAME OF RESOURCE (how determined): 9 / Ruggles House

2. ADDRESS/LOCATION:

South side, AA Highway, about .5 miles west of the intersection of AA Highway and Poplar Flat Road
Herron Hill, KY. 41189

3. UTM REFERENCE:

Quad. Name: Charters

Date: 1991 / Zone: 17 / Accuracy: A
Easting: / 2/ 8/ 2/ 3/ 4/ 3/

Northing: 4 / 2/ 7/ 3/ 2/ 2/ 8/

4. OWNER/ADDRESS:

Box 365 AA Highway/ KY. 9
Herron Hill, KY. 41139

5. FIELD RECORDER/AFFILIATION:

Kate Carothers/ Environment & Archaeology, LLC.

6. DATE RECORDED:

8-12-05

7. SPONSOR:

Cellco Partnership d/b/a Verizon Wireless

8. INITIATION: 3 / Review & Compliance

~~Herron Hill PSC/Collins Cell Site~~

9. OTHER DOCUMENTATION/RECOGNITION:

<input type="checkbox"/> Survey	<input type="checkbox"/> HABS/HAER
<input type="checkbox"/> KY Land	<input type="checkbox"/> Local Land
<input type="checkbox"/> NR	<input type="checkbox"/> NHL

Other:
Report Reference

10. ORIGINAL PRIMARY FUNCTION: 0/ 1 / A /
Single family home

11. CURRENT PRIMARY FUNCTION: 0/ 1 / A /
Single family home

12. CONSTRUCTION DATE: 5 / c. 1880's estimated
/ / / / documented

13. DATE OF MAJOR MODIFICATIONS:

3 / Front porch constructed
1 / Vinyl siding applied; vinyl windows installed

14. CONSTRUCTION METHOD/MATERIAL:

W / 3 / Frame original
/ / subsequent

15. DIMENSIONS:

Height stories 1.5 Width bays 3 Depth bays 2

16. PLAN:

K / Central-passage, single pile first
/ second
/ third

17. STYLISTIC INFLUENCE:

3 / Mid-19th c. ; 2 / Gothic Revival first
/ / ; / second
/ ; / third

18. STYLE DEVELOPMENT:

R / first / second / third

19. FOUNDATION:

TYPE	MATERIAL
2 / Continuous	0/ Undetermined original
/	/ replacement

20. PRIMARY WALL MATERIAL:

0/ Undetermined	original
Y/ Vinyl siding	replacement

21. ROOF CONFIGURATION/COVERING:

CONFIGURATION	COVERING
D / Cross-gabled	7 / Standing-seam metal original
/	/ replacement

22. CONDITION: G / Good

23. MODIFICATION: 2/ Moderate alteration

24. NEGATIVE FILE #: / / /

Write resource # on back of all prints.




COMMENTS/HISTORICAL INFORMATION:

Located on the south side of the AA Highway, about .5 miles from the intersection of the AA Highway and Poplar Flat Road, this property is a 1.5 story frame Gothic-style dwelling clad in vinyl siding, with replacement 1/1 vinyl windows and a cross-gabled asphalt shingle roof. The dwelling rests on a foundation of undetermined material, but the later, c. 1920-1930 front porch rests on a concrete block foundation, with battered wood posts resting on brick pillars. The roof on the house and the porch roof are both standing seam metal; there is a brick chimney centered atop the main house roof. Several outbuildings are located on the property, including a barn, chicken coop, and sheds. A second, frame Gothic-style dwelling is up on the hill above this house, but it was not accessible.

25. SUPPORT RESOURCES: SITE PLAN KEY		FUNCTION	CONSTRUCTION DATE	METHOD/MATERIAL
A	Barn/Storage	c. 1880's	W/3/Frame	
B	Chicken Coop	c. 1880's	W/3/Frame	
C	Storage sheds	c. 1900-1920	W/3/Frame	

26. SITE PLAN (Complete if #25 was answered).



27. MAP (Scan or attach copy of map showing exact location of resource)

